


## Cotton Swabs

Thorough cleaning of a fusion splicer’s optical elements and alignment V-grooves is critical to ensure successful trouble-free splicing operations. CS-1 Cotton Swabs are especially useful for such cleaning operations. The small size of the CS-1 swabs ensures accessibility in tight places and will not leach out chemicals or lint and contaminate optical elements.

DESCRIPTION	PART #
CS-1 Cotton Swabs (pack of 25 each)	S003719



## Temporary Joining Tool

The TJ-03 provides a temporary fiber splice for fiber and cable connections to test equipment such as OTDRs. The TJ-03 uses a precision ceramic V-groove to align up to 12 fibers simultaneously. The fibers are prepared for joining by using standard mass fusion fiber preparation tools (fiber holders, thermal stripper, and cleaver.) Using the TJ-03 in conjunction with an OTDR equipped with an optical switch provides rapid one button optical tests of 12 or 24 fibers.

### Features

- Precision ceramic V-groove alignment
- Built-in magnifier and lamp to inspect fiber placement in V-grooves

DESCRIPTION	PART #
TJ-03 Temporary Splice Kit: Fiber Holders (1 pair) FH-50-12, CT50 Cleaver, RS02 Thermal Stripper, ADC-09 AC Adapter for HJS-02, and the ACC-09 Power Cord	S012772
TJ-03 Temporary Splice (without fiber preparation tools)	S010456